

| | | | | |
|---|------------------|-------------------------|------------------------------------|--------------------------------|
| SERVICE WIPAC BULLETIN | SUBJECT | SPARK PLUG "WHISKERING" | | |
| | Ref. No. | SP.21 | CANCELS | — |
| | AUTHORITY | F.K.M. | INSERT THIS BULLETIN INTO :- | No. 3 MANUAL (TECHNICAL) |
| | DATE OF ISSUE | NOV. '55 | | |

This particular phenomenon is the formation of a fine bridge of conducting material across the plug points which shorts out the plug. It is usually found on plugs in two-stroke engines and is believed to be formed principally from additives in the fuel and lubricating oil. The incidence of "whiskering" has increased considerably since both fuels and oils become adulterated to improve their general performance.

To cure whiskering, or at least diminish the frequency of its occurrence, the following remedies may be employed.

1. Reduce exhaust back pressure, by cleaning out the silencer and pipes.
2. Ensure that the mixture is not too weak.
3. Fit suppressor—5,000 ohms value, or higher, up to 15,000 ohms.
4. Use lubricating oil specially advised for two-strokes.
5. Change grade of petrol used.
6. Fit next harder grade plug.
7. Change shape of plug electrodes as below.

Normal



Change 1



Change 2



NOTE: Plug electrode arrangements 1 and 2 will give improved starting and tick-over on four-stroke engines as well.

THE WIPAC GROUP — BLETCHLEY — ENGLAND
 TELEPHONE: BLETCHLEY 3321 TELEGRAMS: WICOMAGSCO BLETCHLEY



| | | | | |
|---|------------------|---|-----------------------------------|--------|
| SERVICE WIPAC BULLETIN | SUBJECT | RUBBER COVERED BULLET TERMINAL CONNECTORS. | | |
| | Ref. No. | 157 | CANCELS | NIL |
| | AUTHORITY | F.K.M. | INSERT THIS BULLETIN INTO:- | No. 3. |
| | DATE OF ISSUE | 20.1.57 | | |

RUBBER COVERED BULLET TERMINAL CONNECTORS.

You are no doubt familiar with the rubber connectors used on motor cycles with our equipment for connecting up the various circuits. They are made single-way, two-way, three-way and five-way.

Motor cycle dealers report that it is very difficult to push in the bullet connectors, and even more difficult to pull them out. We suggest that you advise them to purchase special pliers for the pushing in part of the operation, which are made by the Ripaults Cable Company, priced about 4s. 0d.

For the pulling out part, we can only suggest that where they are very tight, the rubber part of the connector should be cut away, when the bullet ends will be exposed, and can be forced out by means of a screwdriver blade. This, of course, destroys the connector, but we would like to explain that these connectors should not be re-used in any case, and new ones should be fitted should a dis-connection be necessary.

It is, therefore, wise to suggest that your dealers carry a reasonable stock of the connectors for this purpose.



| | | | | |
|---|------------------|-----------------|-----------------------------------|-----------------------|
| SERVICE WIPAC BULLETIN | SUBJECT | SNAP CONNECTORS | | |
| | Ref. No. | 2327 | CANCELS | Nil |
| | AUTHORITY | F.K.M. | INSERT THIS BULLETIN INTO:- | Nos. 2 & 3. Manual |
| | DATE OF ISSUE | Feb. 1957 | | |

SNAP CONNECTORS.

A number of Motorcycle dealers have raised the question of the difficulty in connecting and disconnecting the bullet type plug terminals from rubber covered metal sockets, which are used in the wiring circuits of Wipac equipment.

Here is the information required which please pass on to the customers staff members concerned:

PULLING OUT.

Grip the insulation of the wire close to the end of the connector about half way along the blades of a pair of ROUND NOSE PLIERS. Then turn the pliers with a circular motion so that one of the blades presses on the end of the rubber forming a lever fulcrum. This will easily withdraw the bullet from its socket.

PUTTING BACK.

Use special split nose pliers made by the RIPAULTS CABLE people (cost about 4/-d.) The action of these is too obvious to need explanation.

NOTE.

The female rubber covered socket portion should not be re-used too often. Frequent removal of the male bullet reduces the contact pressure, and therefore the female portion should be renewed.

--- oo0oo ---



| | | | | |
|---|------------------|-------------------------------|------------------------------------|-----------------------------|
| SERVICE WIPAC BULLETIN | SUBJECT | OXIDISATION OF CONTACT POINTS | | |
| | Ref. No. | 2355 | CANCELS | 1355 |
| | AUTHORITY | F.K.M. | INSERT THIS BULLETIN INTO :- | NOS. 1 AND 2 MANUALS. |
| | DATE OF ISSUE | JUNE 1955 | | |

Most modern magnetos are fitted with tungsten contact points. If magnetos fitted with these points are stored for long periods without use, more particularly under damp or moist conditions, there is a tendency for the contacts to oxidise, with the result that the magneto fails to spark. In order to prevent this happening the contacts of all Wico and Wipac magnetos are treated with a special corrosion resisting material before they leave the works, but if the magneto has been operating to storage, (say on engine test), it is possible that this protection will be removed. If, therefore, a new magneto fails to spark after storage, corrosion of the contact points will be the probable cause. This is easily overcome by wiping the contacts with a wet rag, making certain at the same time that no fluff from the rag is left between the contacts.



| | | | | |
|---|------------------|---|------------------------------------|------------------------------|
| SERVICE WIPAC BULLETIN | SUBJECT | WIPAC SERVICE TOOLS, EXTRACTORS ETC. | | |
| | Ref. No. | 557/T | CANCELS | 125/4 |
| | AUTHORITY | F.K.M. | INSERT THIS BULLETIN INTO :- | No. 3 TECHNICAL MANUAL |
| | DATE OF ISSUE | 15.5.57. | | |


WIPAC SERVICE TOOLS.

| PART NO. | SERIES | DESCRIPTION | PRICE | | |
|----------|-----------------|---|-------|-----|----|
| | | | £. | s. | d. |
| MA383 | A 73 55 | Fixed Contact Setting Tool. | 2. | 10. | 0. |
| 06519 | CJ1 | (2 Peg) Condenser Tool Late Type | | 3. | 0. |
| 00146 | CJ1 | (3 Peg) Condenser Tool Late Type | | 3. | 6. |
| 00562 | 55 | Flywheel Extractor | | 5. | 0. |
| 00586 | BANT 90 | (3 Screws) Flywheel Extractor (3BA) Early Type | | 5. | 0. |
| 00494 | 90 | (4 Screws) Flywheel Extractor (2BA) Late Type | | 5. | 0. |
| S0075 | 90 | (3 Screws) Flywheel Extractor (2BA) (TROJAN) | | 5. | 0. |
| 02100 | C.10.L. Colt | Ignition & Lighting Switch Main Nut Spanner | | 5. | 0. |
| 06508 | C.10.L. Colt | Auto Advance Plate Extractor Tool | | 5. | 0. |
| S0073 | 141 | Flywheel Extractor (PIATTI) | | 5. | 0. |
| S0282 | 150 | Flywheel Extractor (BERINI) short shaft. | | 5. | 0. |
| S0502 | 150 | Flywheel Extractor (KELSTON) long shaft | | 5. | 0. |

THE WIPAC GROUP — BLETCHLEY — ENGLAND
 TELEPHONE: BLETCHLEY 3321 TELEGRAMS: WICOMAGSCO BLETCHLEY



IceniCAM On-Line Library



www.icenicam.org.uk