

All communications to be addressed to the Company—not to individuals.

Telegrams: "Amalcarb, Phone, Birmingham, 6." Telephone: Birmingham, BIRchfields 4571 (P.B.X. 6 lines).
Codes: A.B.C. 5th & 6th Editions, Western Union & Bentley's.

CARBURETTER
MANUFACTURERS AND
GENERAL ENGINEERS



HOLDFORD ROAD
WITTON
BIRMINGHAM :: 6

**Spare Parts List for Type 308/5 Carburetter
AS FITTED TO "CYCLAID" ENGINE.**

Prices stated are those ruling at the date of this list.

Component	Part No.	List Price
Mixing Chamber	308/002	s. d. 8 3
Float Chamber Bottom Feed	308/013	5 6
Float Chamber Cover Bottom Feed	308/015	1 8
Float Chamber Cover Screws	308/018	1
Float complete, Bottom Feed	308/022	2 9
Needle	308/025	1 1
Float Needle, Banjo Type Seating	308/027	1 1
Banjo	308/029	1 8
Banjo Nut	308/030	7
Flange Washer	308/031	2
Flange Stud	308/032	3
Flange Gauze complete	308/034	4
Throttle Valve No. 2	308/037	2 9
Throttle Valve Spring	308/038	4
Throttle Valve Locating Screw	308/039	1
Mixing Chamber Cover	308/040	1 8
Cable Adjuster	308/041	4
Cable Adjuster Locknut	308/042	1
Throttle Needle	308/043	1 8
Throttle Needle Clip	308/044	2
Needle Jet -078	308/045	2 9
Jet Cover	308/068	1 1
Outlet Clip	308/047	10
Outlet Clip Pin	308/048	2
Clip Pin Nut	308/049	1
Cable Nipple	308/051	1
Main Jet, No. 25	124/026	9
Jet Plug Washer	38/023	2
Needle Seating and Banjo Washers	23/110	1
Float Chamber Cover Washer	308/066	2
†Nut for Flange Stud	308/123	2
†Washer for Flange Stud	308/124	1
Air Intake	310/1	8 3

†Earlier Models are fitted with an Aerotight Nut, No. 308/053, instead of this Nut and Washer

IceniCAM Information Service



www.icenicam.org.uk