
Catalogue number REY02
Price code A
Date 20 February 2009
IceniCAM Information Service

25 MARCH 1965

VOL 114 No 3223

## Motor Cycle





Prototype frames, suggests Ken, should be made on the weak side so that faults are shown up more readily in tests. Far left, a prototype moped pounds the pavé surface of MIRA. Left, is the result. Before production starts, the frame would be strengthened at the point where it failed.